

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

8. Description of Work Accomplished

(If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)

Removed original engine oil cooler and attaching bracket from base of engine. Located, drilled and painted new bracket supplied from Pacific Oil Cooler Services and installed at location of original bracket. Painted and installed new aluminum oil cooler P/N G723838, S/N 2088 supplied from Pacific Oil Cooler Services. New oil cooler is a bolt on replacement featuring identical oil line fittings, vernatherm mount design and related fittings. Aircraft equipment list and weight and balance updated. Instructions for Continued Airworthiness (ICA): Inspect oil cooler and associated fixtures, hoses, mounts and hardware for condition and security at regular scheduled maintenance intervals. ICA attached.

***** NOTHING FOLLOWS *****

Additional Sheets Are Attached